BIM QA/QC *process*

Organization Quality Standards, Quality Documents & earlier project reference

Project In

Quality Planning for each project

Quotation

Sample Project

Prepare List of Quality Parameters

Prepare Responsibility Matrix [RACI Chart]

Customer Feedback

Prepare Preliminary Quality List

Prepare Quality Register

Actual Project Execution

Prepare a Final Quality List

Quality Check

1st Level - Self QC
2nd Level - Peer QC
3rd Level - Random Audit by Quality Manager
Update Quality register & if necessary update Quality List / Quality Parameter List

Customer Feedback

If any changes recommended by client
Part of SoW (Scope of Work) : Iteration in above process
Any new changes included in SOW : Start Engineering Change Management Process

Final Delivery

hitech
Your Partner in Digital Excellence
Since 1992

https://www.hitechcaddservices.com
info@hitechcaddservices.com

Copyright © 2018 Hitech CADD Services. All Rights Reserved.